



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Mock Inspection Report

6932 Hawthorne Trace Lane, Riverview, FL, USA

Jan 19, 2022

Performed by **Aaron birk**

This is a mock inspection report to demonstrate that the inspector has performed an inspection according to the [InterNACHI® Standards of Practice](#).

Roof

View the InterNACHI® “Roof” inspection standard at <https://www.nachi.org/sop.htm#roof>.

Items Inspected

Roof-Covering Materials

No Defect(s) Observed

Gutters

No Defect(s) Observed

Downspouts

No Defect(s) Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

**Vents, Flashing, Skylights, Chimney, and Other
Roof Penetrations**

No Defect(s) Observed

**General Structure of the Roof (from the readily
accessible panels, doors or stairs)**

No Defect(s) Observed

System Descriptions

The Type of Roof-Covering Materials

- Asphalt Shingle

Reported Observations

Did you observe any indications of active roof leaks?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Exterior

View the InterNACHI® “Exterior” inspection standard at
<https://www.nachi.org/sop.htm#exterior>.

Items Inspected

Exterior Wall-Covering Materials

No Defect(s) Observed

Eaves, Soffits and Fascia

No Defect(s) Observed

Windows (a representative number)

No Defect(s) Observed

All Exterior Doors

No Defect(s) Observed

Flashing and Trim

No Defect(s) Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Adjacent Walkways and Driveways

No Defect(s) Observed

Stairs, Steps, Stoops, Stairways and Ramps

No Defect(s) Observed

Porches, Patios, Decks, Balconies and Carports

No Defect(s) Observed

Railings, Guards and Handrails

Not Inspected | Not Present

**Vegetation, Surface Drainage, Retaining Walls
and Grading of the Property (where they may
adversely affect the structure due to moisture
intrusion)**

No Defect(s) Observed

System Descriptions

The Type of Exterior Wall-Covering Materials

- Vinyl



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Reported Observations

Did you observe any improper spacing between intermediate balusters, spindles or rails?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Basement, Foundation, Crawlspace & Structure

View the InterNACHI® “Basement, Foundation, Crawlspace & Structure” inspection standard at <https://www.nachi.org/sop.htm#basement>.

Items Inspected

Foundation

No Defect(s) Observed

Basement

Not Inspected | Not Present

Crawlspace

Not Inspected | Not Present

Structural Components

No Defect(s) Observed

System Descriptions

The Type of Foundation

- Concrete slab



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

The Location of the Access to the Under-Floor Space

- Not present

Reported Observations

Did you observe indications of wood in contact with or near soil?

Not Observed

Did you observe indications of active water penetration?

Not Observed

Did you observe indications of possible foundation movement?

Not Observed

Did you observe cutting, notching or boring of framing members?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Heating

View the InterNACHI® “Heating” inspection standard at
<https://www.nachi.org/sop.htm#heating>.

Items Inspected

Heating System (using normal operating controls)

No Defect(s) Observed

System Descriptions

Location of the Thermostat for the Heating System

- Hallway wall at front door entrance

The Energy Source

- Electricity

The Heating Method

- Heat pump

Reported Observations



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Did you observe any heating system that did not operate?

Not Observed

Did you observe that the heating system was inaccessible?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Cooling

View the InterNACHI® “Cooling” inspection standard at <https://www.nachi.org/sop.htm#cooling>.

Items Inspected

Cooling System (using normal operating controls)

No Defect(s) Observed

System Descriptions

The Location of the Thermostat for the Cooling System

- Hallway wall near front door entrance

The Cooling Method

- Central air conditioning system

Reported Observations

Did you observe any cooling system that did not operate?

Not Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

**Did you observe that the cooling system was
inaccessible?**

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Plumbing

View the InterNACHI® “Plumbing” inspection standard at <https://www.nachi.org/sop.htm#plumbing>.

Items Inspected

Main Water Supply Shut-Off Valve

Not Inspected | Inaccessible

Main Fuel Supply Shut-Off Valve

No Defect(s) Observed

Water Heating Equipment (including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing)

No Defect(s) Observed

Interior Water Supply (including all fixtures and faucets, by running the water)

No Defect(s) Observed

All Toilets (for proper operation by flushing)

No Defect(s) Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

All Sinks, Tubs and Showers (for functional drainage)

No Defect(s) Observed

Drain, Waste and Vent System

No Defect(s) Observed

Drainage Sump Pumps (with accessible floats)

Not Inspected | **Not Present**

System Descriptions

Whether the Water Supply is Public or Private (based upon observed evidence)

- Public water supply

The Location of the Main Water Supply Shut-Off Valve

- Could not locate , home is a townhome , waiting on reply from property management



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

The Location of the Main Fuel Supply Shut-Off Valve

- Outside wall with adjoining units shutoff

The Location of Any Observed Fuel-Storage System

- Not present

The Capacity of the Water Heating Equipment (if labeled)

- 60 gallon

Reported Observations

Did you observe deficiencies in the water supply?

Not Observed

Did you observe deficiencies in the installation of hot and cold water faucets?

Not Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Did you observe active plumbing water leaks?

Not Observed

Did you observe toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Electrical

View the InterNACHI® “Electrical” inspection standard at
<https://www.nachi.org/sop.htm#electrical>.

Items Inspected

Service Drop

Not Inspected | **Not Present**

**Overhead Service Conductors and
Attachment Point**

Not Inspected | **Not Present**

Service Head, Gooseneck and Drip Loops

Not Inspected | **Not Present**

Service Mast, Service Conduit and Raceway

No Defect(s) Observed

Electric Meter and Base

No Defect(s) Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Service-Entrance Conductors

No Defect(s) Observed

Main Service Disconnect

No Defect(s) Observed

**Panelboards and Over-Current Protection
Devices (circuit breakers and fuses)**

No Defect(s) Observed

Service Grounding and Bonding

No Defect(s) Observed

Switches, Lighting Fixtures and Receptacles

No Defect(s) Observed

**Ground-Fault Circuit Interrupter Receptacles and
Circuit Breakers**

No Defect(s) Observed

**Presence of Smoke and Carbon-Monoxide
Detectors**

No Defect(s) Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

System Descriptions

The main service disconnect's amperage rating (if labeled)

- 150 amp

The Type of Wiring Observed

- Copper

Reported Observations

Did you observe deficiencies in the integrity of the service-entrance conductors' insulation, drip loop, and vertical clearances from grade and roofs?

Not Observed

Did you observe any unused circuit-breaker panel opening that was not filled?

Not Observed

Did you observe the presence of solid conductor aluminum branch-circuit wiring, if readily visible?

Not Observed



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Did you observe an issue with any tested receptacle?

Not Observed

**Did you observe the absence of smoke and/or carbon
monoxide detectors?**

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Fireplace

View the InterNACHI® “Fireplace” inspection standard at
<https://www.nachi.org/sop.htm#fireplace>.

Items Inspected

**Fireplaces and Chimneys (readily accessible
and visible portions)**

Not Inspected | **Not Present**

Lintels Above the Fireplace Openings

Not Inspected | **Not Present**

**Damper Doors (by opening and closing them,
if readily accessible and manually operable)**

Not Inspected | **Not Present**

Cleanout Doors and Frames

Not Inspected | **Not Present**

System Descriptions

The Type of Fireplace

- Not present



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Reported Observations

Did you observe evidence of joint separation, damage or deterioration of the hearth, hearth extension or chambers?

Not Observed

Did you observe manually operated dampers that did not open and close?

Not Observed

Did you observe the lack of a smoke detector in the same room as the fireplace?

Not Observed

Did you observe the lack of a carbon-monoxide detector in the same room as the fireplace?

Not Observed

Did you observe cleanouts not made of metal, pre-cast cement, or other non-combustible material?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Attic, Insulation & Ventilation

View the InterNACHI® “Attic, Insulation & Ventilation” inspection standard at <https://www.nachi.org/sop.htm#attic>.

Items Inspected

Insulation in Unfinished Spaces (including attics, crawlspaces and foundation areas)

No Defect(s) Observed

Ventilation of Unfinished Spaces (including attics, crawlspaces and foundation areas)

No Defect(s) Observed

Mechanical Exhaust Systems in the Kitchen, Bathrooms and Laundry Area

No Defect(s) Observed

System Descriptions

The Type of Insulation Observed

- Fiberglass roll



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

The Approximate Average Depth of Insulation

- 4 inches

Reported Observations

Did you observe the general absence of insulation or ventilation in unfinished spaces?

Not Observed



International Association of Certified Home Inspectors

Visit us online at [NACHI.ORG](https://www.nachi.org)

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

Doors, Windows & Interior

View the InterNACHI® “Doors, Windows & Interior” inspection standard at <https://www.nachi.org/sop.htm#doors>.

Items Inspected

Doors and Windows (a representative number, by opening and closing them)

No Defect(s) Observed

Floors, Walls and Ceilings

No Defect(s) Observed

Stairs, Steps, Landings, Stairways and Ramps

No Defect(s) Observed

Railings, Guards and Handrails

No Defect(s) Observed

Garage Vehicle Doors

Not Inspected | **Not Present**

System Descriptions



International Association of Certified Home Inspectors

Visit us online at NACHI.ORG

World Headquarters
1750 30th St Ste 301
Boulder, CO 80301

A Garage Vehicle Door (as manually-operated or installed with a garage door opener)

- Not present

Reported Observations

Did you observe improper spacing between intermediate balusters, spindles and rails for steps, stairways, guards or railings?

Not Observed

Did you observe photo-electric safety sensors that did not operate properly?

Not Observed

Did you observe any window that was obviously fogged or displayed other evidence of broken seals?

Not Observed